METACRYLICS SILICONE ROOF TOP PENETRATION ROOF DETAILS

DRAWING INDEX:

C-01 - COVER PAGE & DRAWING INDEX SHEET

A-01 - WALKING PAD

A-02 - METAL PARAPET CAP AND BASE FLASHING

A-03 - SKYLIGHT

A-04 - PLUMBING VENT

A-05 - ROOF DRAIN

A-06 - SCUPPER

A-07 - CURB

A-08 - RAISED CURB FOR ROOFTOP EQUIPMENT

A-09 - BASE FLASHING WITH COUNTER FLASHING

A-10 - ROOF PERIMETER EDGE

A-11 - GUTTER





SILICON SYSTEM DETAILS

SEAL:

REV:

JOB NUMBER:

SCALE:

DATE:


09-25-17


DHALSELL

CHECKED BY:

SHEET:

C-01





METAL PARPAPET CAP & BASE FLASHING

NOTES:

1. THE PRIMER APPLICATION IS REQUIRED BEFORE THE 3-COURSING IS STARTED

JOB NUMBER:

SCALE:

09-25-17

DHALSELL

CHECKED BY:

SHEET:

A-02





SILICONE SYSTEM DETAILS

SEAL:

REV:

JOB NUMBER:

SCALE:


09-25-17

DHALSELL

CHECKED BY:

SHEET:

A-03



SKYLIGHT

NOTES:

1. THE PRIMER APPLICATION IS REQUIRED BEFORE THE 3-COURSING IS STARTED





SILICONE SYSTEM DETAILS

SEAL:

REV:

JOB NUMBER:

SCALE:


^{ATE:} 09-25-17

DHALSELL

CHECKED BY:

SHEET:

A-04



PLUMBING VENT

NOTES:

1. THE PRIMER APPLICATION IS REQUIRED BEFORE THE 3-COURSING IS STARTED





SILICONE SYSTEM DETAILS

SEAL:

REV:

JOB NUMBER:

SCALE:

DATE:


09-25-17

DRAWN BY: **DHALSELL**

CHECKED BY:

SHEET:


A-05





ROOF DRAIN

NOTES:

1. THE PRIMER APPLICATION IS REQUIRED BEFORE THE 3-COURSING IS STARTED







RAISED CURB FOR ROOFTOP EQUIPMENT

JOB NUMBER:

SCALE:

09-25-17

DHALSELL


CHECKED BY:

SHEET:

80-A

NOTES:

1. THE PRIMER APPLICATION IS REQUIRED BEFORE THE 3-COURSING IS STARTED



BASE FLASHING WITH COUNTER FLASHING

NOTES:

- 1. THE PRIMER APPLICATION IS REQUIRED BEFORE THE 3-COURSING IS STARTED
- 2. TOP OF THE FLASHING NEEDS TO BE SEALED TO WALL





SILICONE SYSTEM DETAILS

SEAL:

REV:

JOB NUMBER:

SCALE:


09-25-17


DHALSELL

CHECKED BY:

SHEET:

A-09





GUTTER

NOTES:

- 1. THE PRIMER APPLICATION IS REQUIRED BEFORE THE 3-COURSING IS STARTED
- 2. NEW METAL DRIP EDGE OR PARAMETER FLASHING NEEDS TO BE TREATED WITH EITHER VINEGAR OR A PRODUCT THAT WILL REMOVE THE OILY RESIDUE BEFORE PROCEEDING TO APPLY COATING PRODUCTS OVER THE NEW METAL SURFACE.



SILICONE SYSTEM DETAILS

SEAL:

REV:

JOB NUMBER:

SCALE:

09-25-17

DRAWN BY:

DHALSELL

CHECKED BY:

SHEET:

A-11